

164673



SITE INSPECTION REVIEW FORM

SITE NAME: CAMDEN MUNICIPAL WELLS

ALIASES: _____

SITE I.D.#: NJD980769087

| <u>ITEM</u> | <u>COMPLETE ?</u> | |
|---|-------------------------------------|--------------------------|
| | <u>YES</u> | <u>NO*</u> |
| SITE LOCATION (INCLUDING MAP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| SITE BACKGROUND | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| HRS PRE - SCORE (PRELIMINARY + PROJECTED) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| POTENTIAL FOR DIRECT CONTACT | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| CONCLUSIONS + RECOMMENDATIONS | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| REFERENCES | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

HRS PRE-SCORE: PRELIMINARY SCORE = 42-24

PROJECTED SCORE = 42-24

COMMENTS:

Potable water supply is potentially at risk to a large population ($\approx 50,000$). The history of ground water contamination is well-documented. The maximum targets scoring is indicative of the contamination threat present, although the source(s) is/are difficult to establish. HIGH PRIORITY.

NJDEP has been compiling hydrologic information, through its DWR/Bureau of Ground Water Pollution Assessment. Further sampling is not needed at this time. NJDEP is currently identifying responsible parties for the Morris - Delair Wellfield.

REVIEWED BY: LARRY TANNENBAUM

DATE: FEB. 16, 1990

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS